

## Pomes, Michael

---

**From:** Sac & Fox Truck Stop <sacfoxtsmgr@jbntelco.com>  
**Sent:** Friday, August 28, 2015 3:18 PM  
**To:** Drouare, Douglas  
**Subject:** RE: Sac and Fox Truck Stop  
**Attachments:** 201508281512.pdf

**Categories:** EZ Record - Shared

Here is the form mostly filled out and an update. Thanks Theresa

---

**From:** Drouare, Douglas [mailto:drouare.douglas@epa.gov]  
**Sent:** Wednesday, August 26, 2015 8:08 AM  
**To:** Sac & Fox Truck Stop; mark.junker@sacfoxenviro.org  
**Cc:** Bosch, Raymond; Stockdale, Margaret; Bynum, Whitney  
**Subject:** RE: Sac and Fox Truck Stop  
**Importance:** High

Thanks for the report Theresa. This report should suffice to meet your reporting requirements under 40 CFR, Part 280.62, 20 Day Site Check Report. It is not formatted in a manner typical of professional consultants in the field but it gets the job done. It was a few days late but your prior phone call to us explaining why is adequate explanation. We have discussed the need for the updated UST Notification form and you have indicated that you are still in the process of completing it and will transmit it shortly.

The next regulatory responsibility will be to continue free product recovery efforts and begin to characterize the extent of impact to the soil and groundwater and evaluate potential exposure threats (i.e. surface water bodies, utility trenches/lines, drinking water sources, vapors, etc.). This responsibility is addressed under 40 CFR Part 280.63. The results of these efforts should be reported in the 45 Day Initial Site Characterization Report. This report would be due to us on September 6, 2015.

Here is a link to 40 CFR, Part 280: the federal regulations related to leaking underground storage tank actions.

<http://www.epa.gov/region4/usttoolkit/pdfs/regulatorycompliance/40cfr280.pdf>

Listed below is the contact information we have for this particular release:

Responsible Party

Sac & Fox Tribe  
Mark Junker & Jim Jensen  
305 North Main, Reserve, Kansas, 66434  
(785) 742-4706, alt. (734) 742-7471, fax (785) 742-2180  
[mark.junker@sacfoxenviro.org](mailto:mark.junker@sacfoxenviro.org)

Property Owner

Sac & Fox Tribe  
Sac & Fox Truck Stop  
Theresa Armbruster, Manager  
1346 Highway 75, Powhattan, Kansas, 66527  
(785) 467-5354, alt. (402) 245-1236  
[sacfoxtsmgr@jbntelco.com](mailto:sacfoxtsmgr@jbntelco.com)

Please review and provide corrections to this information if necessary.

If you are unfamiliar with the procedures used to investigate/evaluate leaking underground storage tank (LUST) sites and risk based corrective action (RBCA), you can seek guidance from a number of state resources such as that found via the links below:

<http://www.kdheks.gov/tanks/index.html>

[http://www.kdheks.gov/tanks/risk\\_based\\_corrective\\_action.htm](http://www.kdheks.gov/tanks/risk_based_corrective_action.htm)

As the services related to LUST investigation and RBCA can be highly specialized and technical, we strongly recommend you consider hiring a professional consultant who is experienced in this field. Attached are several resources that our regional states utilize to direct responsible parties to experienced consultants. These are not all inclusive lists and do not represent an endorsement from any federal or state governmental organization.

If you have any questions, please contact us.

Thank you,

Douglas E. Drouare, CPG  
USEPA, Region 7, AWMD - STOP  
11201 Renner Boulevard  
Lenexa, Kansas 66219  
(913) 551-7299  
drouare.douglas@epa.gov

---

**From:** Sac & Fox Truck Stop [mailto:sacfoxtsmgr@jbntelco.com]  
**Sent:** Thursday, August 20, 2015 3:08 PM  
**To:** Drouare, Douglas  
**Subject:** Sac and Fox Truck Stop

Here is a run down of actions taken regarding the ruptured tank at the Truck Stop. Thanks Theresa any questions please call 402-245-1236